### UNCLASSIFIED

# AD NUMBER AD514530 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

### TO:

Approved for public release; distribution is unlimited.

### FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; 12 AUG 1970. Other requests shall be referred to Office of the Adjutant General, Washington, DC 20301.

### **AUTHORITY**

AGO ltr 29 Apr 1980 ; AGO ltr 29 Apr 1980

# SECURITY MARKING

The classified or limited status of this report applies to each page, unless otherwise marked.

Separate page printouts MUST be marked accordingly.

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S.C., SECTIONS 793 AND 794. THE TRANSMISSION OR THE REVELATION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSONOIS PROHIBITED BY LAW.

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

THIS REPORT HAS BEEN DELIMITED

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200.20 AND

NO RESTRICTIONS ARE IMPOSED UPON

ITS USE AND DISCLOSURE.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED.



145

### DEPARTMENT OF THE ARMY

OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

AGDA -A (M) (12 Mar 71) FOR OT UT 703266

19 March 1971

SUBJECT: Operational Report - Lessons Learned, Headquarters, 145th Aviation Battalion, Period Ending 31 July 1970 (U)

SEE DISTRIBUTION

THIS DOCUMENT CONFAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18, U.S. C. S'CTION 793 AND 794. ITS TRANSMISSION OR THE REVOLUTION OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAWS.

1. The attached report is forwarded for review and evaluation in accordance with para 4b, AR 525-15.

2. The information contained in this report is provided to insure that lessons learned during current operations are used to the benefit of future operations and may be adapted for use in developing training material.

3. Information of actions initiated as a result of your evaluation should be forwarded to the Assistant Chief of Staff for Force Development, ATTN: FOR OT UT within 90 days of receipt of this letter.

BY ORDER OF THE SECRETARY OF THE ARMY:

l Incl

VERNE L. BOWERS
Major General, USA
Acting The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

US Army Materiel Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Armor School

US Army Aviation School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Ordnance School

US Army Transportation School

DDC PREMAR APR 12 1971

Regraded unclassified when separated from classified inclosure.

### DISTRIBUTION (Cont'd)

Copies furnished: Office, Chief of Staff, US Army Deputy Chiefs of Staff Chief of Research and Development Assistant Chiefs of Staff Chief of Engineers Commanding Generals US Army Flight Training Center Deseret Test Center III Corps, ATTN: Director, Project MASSTER Commandant of the Marine Corps Defense Documentation Center USAF Project RAND Commanding Officers US Army Limited War Laboratory US Army Logistics, Doctrine Systems & Readiness Agency US Army Aviation Test Activity

US Army Mobility Equipment Research & Development Center

DEPARIMENT OF THE TARMY
HEADQUARTERS, 145TH AVIATION BATTALION (COMBAT)
APO San Francisco 96227

### "FIRST IN VIEINAN"

AVB.CA-BC

12 August 1970

SUBJECT: Operational Report - Lesson Learned, 145th Aviation Battalion (Combdt), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

SEE DISTRIBUTION

### 1. Operations: Significant Activities:

a. Mission: The overall mission of this Battalion did not change during the reporting period. This mission is to augment the capabilities of II Field Forces Vietnam and the Republic of Vietnam forces which operate in the III Corps Tactical Zone.

### b. Organization:

- (1) No organizational changes took place during this reporting Period.
- (2) The 334th Avn Co (Atk Hel) was relocated to Phu Loi, APO San Francisco 96289, effective 6 May 1970. The 11th Avn Bn (Cbt) will furnish the 334th Avn Bn (Atk Hel) with medical support at their new location.
- (3) As of 31 July 1970, the Battalion was organized as shown by inclosure 1.

### c. PERSONNEL:

- (1) Command and Staff changes and present status:
- (a) Commanding Officer, 145th Aviation Battalion (Combat) (19 May 70)

Outgoing: LTC Jack Seliskar 470-26-3170 IN Outgoing: LTC Calvin G Dodd 455-46-1580 IN (12 Aug 70) Incoming: LTC William H Dillard 226-30-2072 IN (12 Aug 70)

(b) Battalion Executive Officer (27 Jul 70)

Outgoing: MAJ Thomas R Wolf 378-34-6725 IN Incoming: MAJ Bobbie G Pedigo 405-40-3223 AR

(c) Battalion Adjutant

CPT Michael J Scanlon

228-62-8011 AR

FOR OT UT 703226 Inclosure

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

CONFIDENTIAL

1

AVBACA-BC 12 ingust 1970 SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Inding 31 July 1970 RCS CEFOR-65 (R2) (d) Battalion S-2 CPT Ihomas A Shtogren 506-52-4374 AR (e) Battalion S-3 (5 Jul 70) Outgoing: MAJ Robert H Smith 257-52-2769 IN 567-52-7158 IN Incoming: MAJ Lyman C Culver (f) Battalion S-4 (4 Jun 70) 274-36-3903 IN 466-68-3051 IN Cutgoing: CPT Billy G Murphy Incoming: CPT Jerry R Hill (g) Commanding Officer HHC (26 Jul 70) 313-38-9799 IN 506-52-4374 AR Outgoing: CPF Jerry D McGlothlin Incoming: CPF Thomas A Shtogren (h) Commanding Officer 68th Avn Co (Aslt Hel) (4 May 70) Outgoing: MAJ Luther L French
Incoming: MAJ Mitchell G Thompson 436-54-2175 IN 413-50-5178 FA (i) Commanding Officer 118th Avn Co (Aslt Hel) (5 Jul 70) 419-40-1443 IN Outgoing: MAJ Michael P Hefferman 257-52-2769 IN Incoming: MAJ Robert H Smith (j) Commanding Officer 190th Avn Co (Aslt Hel) MAJ Dale W Pierce 261-44-4425 IN (k) Commanding Officer 334th Avn Co (Atk Hel) MAJ John R McQuestion 264-52-3902 IN (1) Commanding Officer 324th ASD 446-22-0270 IN MAJ Jack A King

(2) Unit Strength: On 31 July 1970, the Battalion was at 90% total strength. Individual unit strengths are shown by Inclosure 2.

INCL

2

AVBACA-BC

SUBJECT: Operational Report - Lossons Learned, 145th Aviation
Battalion (Combat), Period Ending 31 July 1970 RCS C3FOR-65(R-2)

d. Aircraft Status: At the end of this reporting period the Battalion had on hand SO% of the total aircraft authorized. Aircraft status as of 31 July 1970, classified by unit and type of aircraft, is shown in Inclosure 3.

### o. Chronology of Significant Events:

- (1) From 26 April 1970 through 30 Juno 1970 the 145th Aviation Battalion (Combat) provided support to United States and Allied Forces operating in Cambodia. Missions were flown daily as directed by II FFV, AAE. The main units supported by the 145th Aviation Battalion (Combat) were 25th ARVN Div., 11th ACR, 3/9th Inf, and 25th Inf Div. As a result of this operation the 145th Aviation Battalion (Combat) was credited with killing 166 enomy soldiers, destroying 309 structures and 5 Sampans. There were 17 reported secondary explosions.
- (2) The 190th Avn Co (Aslt Hol) bogan its Vietnamese Air Force (VNAF) Improvement and Modornization program on 15 June 1970 with the arrival of seven (7) VNAF EM ranging in grados from E-4 through E-3. These personnel were turbine engine repairmen, their experience levels ranged from 6 menths to 12 years. On 1 July 1970, the unit received 25 VNAF enlisted personnel in grades E-1 and E-2. These personnel were UH-1 helicopter repairmen, trained at the US Army Transportation School at Fort Eustis, Virginia. Prior to thoir arrival they had no provious practical experience. On 16 July 1970, a VNAF maintenance crew assisted by mechanics of the 190th Avn Co (Aslt Hel) performed the 5th periodic Inspection on UH-1D Serial No. 69-15755, assigned to Headquartors, 12th Aviation Group (Combat). On or about 3 August 1970 a VNAF maintonanco crew will perform a complete periodic inspection on a UH-1 typo aircraft. It is intended that all assistance rendered by US porsonnel will be on an "as needed" basis only. The overall quality of work performed by the VNAF maintonance personnel has been exceptionally high. The Engine personnel have displayed an excellent working knowledge of the T-53 engine, this is largely due to their high experience level. The mechanics have consistantly displayed an eager willingness to learn and to employ the skills and knowledge they acquired while at the transportation school.
- (3) On 1 June 1970 USARV directed that no TOE/HTOE equipment belonging to the 190th Avn Co (Aslt Hel) could be laterally transfered without their approval.

INCL

3

AVBACA-BC

SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS SCFOR-65(R-2)

- (4) One May was the third day of a special mission requiring the 334th Avn Co (Atk Hel) to provide 4 light fire teams on 5 minute standby 24 hours a day. Five fire teams were staged at Cu Chi using 1 team as a spare. The Operations' section utilized an area provided by the 269th Aviation Battalion (Combat). The problem area encountered in this type mission was communications, primarily because all ground to air communications with supported units was with FM radios. The aircraft traveled approximatly 25 miles from Cu Chi to the area of operation. The only ground ratio this unit has by TO&E is FM, 33B, and UHF vehicle mounted radios. This proved to be unsatisfactory because of the necessity to use makeshift antennas. Aircraft on assigned missions were required to use their FM radio to coordinate with the unit being supported. Due to the lack of communications, Operations had no contact with the aircraft until the mission was completed and the aircraft changed to the company FM frequency. While the mission was in progress, the company was in the process of making a move from Bien Hoa to Phu Loi. This necessitated radio communications at three different locations. The 334th Avn Co (Atk Hel) was unable to monitor the Battalion secure frequency due to the limited radio capability. Land lines between Cu Chi and Bien Hoa were completely unsatisfactory, this caused a delay in reports and coordination between Battalion Operation Center and the 334th Avn Co (Atk Hel). During the special operation the company lost two aircraft due to combat damage bringing our total assets to seventeen AH-1G and two UH-1 aircraft. On 4 May, the rear element at Bien Hoa received the order to complete the move to Phu Loi by 5 May. On 6 May the Operation at Cu Chi was terminated and all personnel and equipment returned to Phu Loi. Missions for the remainder of May and the first of June were normal OPCON and ESB type missions assigned by II FFV, ide.
- a. On 19 June, the 334th Avn Co (Atk Hel) was assigned a special mission to be staged from Quan Loi. The requirement was to furnish two light fire teams on a 24 hours bases. The mission placed an additional burden on the unit because of the extra blaic time required to transport equipment and personnel from Phu Loi to Quan Loi. This burden was partially alleviated by a courier flight performed once a day by Battalion. The mission was terminated on 30 June and reassigned again 6 July. Due to the great distance between Quan Loi and the LZ's it is necessary to stage from unimproved areas without refueling or rearming facilities. The 334th Avn Co (Atk Hel) does not have the organic equipment required to maintain POL and rearming points other than the one located in the company area. The average daily requirement is 10 AH-1G and 1 UH-1 aircraft. All missions are rotated between the three platoons on a daily basis with the exception of the mission at Quan Loi which is rotated every six days.

b. The 334th Avn Co (Atk Hel) is now required to maintain it's own ammunition supply point. This places an additional work load on the ammunition section. The section is authorized 10 enlisted men and presently has 5 assigned.

- (5), Bien Hoa Air Base was subjected to 5 rocket and mortar attacks during this reporting period. The 145th Aviation Battalion (Combat) area was hit 3 times resulting in 1 Vietnamese civilian KIA, 9 US WIA and 1 building damaged.
- (6) The following is a list of the number of awards submitted and received by individuals in this battalion.

SUBMITTED	AWARD	RECEIVED
2	Silver Star	3
0	Legion of Merit	1
63	Distinguished Flying Cross	45
7	Soldiers Medal	2
1	Bronze Star "V"	1
155	Bronze Star	162
41	Air Medal "V"	62
303	Air Medal	312
7	Army Commendation Medal "V"	4
498	Army Commendation Medal	592
13	Purple Heart	13

- 2. Lessons Learned: Commander's Observations, Evaluation, and Recommendations:
  - a. Personnel: None
  - b. Intelligence: None
  - c. Operations:

Mission Coordination

- (1) OBSERVATION: In too many instances, coordination for missions is incomplete or inadequate.
- (2) EVALUATION: Coordination for many of the missions received by the 145th Avn Bn (Cbt) consist only of coordinates, call sign and a frequency. Many blade hours are wasted by having the wrong frequency, or a change in mission unknown to anyone but the supported unit.
- · (3) RECOMMENDATION: That at the time the mission is assigned to the battalion, the following information be furnished:
  - (a) Name of supported unit
  - (b) Location of supported unit
  - (c) Call sign
  - (d) Primary and alternate frequencies

Excess Rearming Time For AH-1G

- (1) OBSERVATION: There is an excessive time lapse for AH-1G rearming turn around.
- (2) EVALUATION: The AH-1G in the light hog configuration carries 52, 2.75 inch rockets, 400 rounds of 40MM, and 3000 rounds of 7.62 minigun ammunition. Systems have been developed to facilitate rapid rearming and faster turn around time. It has been the experience of aviators in the 334th Avn Co (Atk Hel) that few rearm points in MR III have personnel trained in rearming the AH-1G aircraft. Because of this the aircraft has to be shut down. Both pilots then dismount and rearm the aircraft. Rearming time varies, however, with fully expended weapons systems the average time spent on the ground at the rearm point is thirty minutes. This does not take into consideration any problems encountered in the weapons system, ammunition not being broken down, and refueling time. Consequently, turn around time is greatly increased, and the combat efficiency of the AH-1G is significantly impaired.

12 August 1970

SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

### (3) RECOMMENDATION:

- (a) That all major rearm points in MR III have trained personnel on hand for the rapid rearming of AH-1G helicopters.
- (b) That all units responsible for major rearm points give consideration to providing at least one person trained in the various armament systems installed on AH-1G aircraft.

Improved AH-1G Oil Cooler Cleaning Procedures

- (1) OBSERVATION: The failure rate of oil cooler fan on the AH-1G is extremely high if it is not properly cleaned.
- (2) EVALUATION: Due to the extreme environmental condition, the oil cooler fan bearings become dirty and cause the fan to fail. The 334th Avn Co (Atk Hel) has found that cleaning the assembly with solvent and rinsing with water has partially alleviated the problem.
- (3) RECOMMENDATION: That this method of cleaning be incorporated in the PMI. All that is required to clean the assembly is to remove the screen and blades, wash with solvent, and rinse with water.

Inadequate Instrumentation of the AH-1G Aircraft

- (1) OBSERVATION: There is a considerable delay in the application of MWOs and other procedures to repair inoperable attitude indicators.
- (2) EVALUATION: Due to the nonavalibility of attitude indicators and MWO kits, many aircraft are required to fly with only one attitude indicator. In some older aircraft both the pilots and co-pilots attitude indicators are inoperable. This situation is extremely hazardous to safety, especially during the monsoon season. At times, aircraft are unable to take off before daylight and must return to home station before dark due to the lack of attitude indicators.
- (3) RECOMMENDATION: That immediate steps be taken in aviation logistics channels to alloviate the shortage of attitude indicators and MWO kits.

Combat Damage Assessment and KBA figuires

(1) OBSRVATION: Damage or results of AH-1G airstrikes are seldom received at unit level.

12 August 1970

- SUBJECT: Operational Report Lessons Learned, 1/5th Aviation Battalion (Combat), Period Shiling 31 July 1970 RCS CSFOR-65 (R-2)
- (2) EVALUATION: Due to the nature of the mission of the 334th Avn Co (Atk Hel), (i.e. not working directly for any unit but supporting most of the units in MR III) it seldon receives any combat demage assessment or KBA figures from most missions flown. This makes many after action reports inaccurate because the mission commander must estimate results.
- (3) RECOMBINDATION: That a system be implemented requiring supported units to submit a combat damage and KBA report to 11 FMV AAE, and that the results be called down to the 145th Avn Bn (Cbt) operation center.

### VNAF I&M Program

- (1) OBSERVATION: Excess non-mission essential equipment causes the deactivating unit unnecessary problems once it enters the programing phase. Many items of equipment could be laterally transferred within the battalion before the deactivating unit begins the VMAF I&M Program.
- (2) EVALUATION: After the 100% inventory is submitted all lateral transfers must be approved by USARV. This process is time consuming and results in a 3 or 4 day lag before actual transfer is accomplished. Disposition of turn in of all TOE equipment is also time consuming. Lateral transfer would be more adventageous for both the deactivating unit and the gaining unit.

### (3) RECOMMENDATION:

- (a) That deactivating units conduct an inventory prior to coming under the I&M program and furnish a list of equipment available for lateral transfer to companies within the battalion.
- (b) That the deactivating unit review their TOE/MTOE equipment for excess and non-mission essential items and accomplish turn in action in accordance with USARV Reg 310-33 dated 16 June 67.
- (4) COMMAND ACTION: Correspondence is being forwarded to the 12th Avn Gp (Cbt) recommending that the above be adopted as policy.

### Discharging Of Weapons From Helicopters

- (1) OBSERVATION: During the past few months, the 145th Avn Bn (Cbt) has been contacted in regards to several incidents involving the firing of weapons from helicopters.
- (2) EVALUATION: The majority of the above firing incidents involved one UH-1 helicopter. MACV Directive 525-13 Sec 7-c, Annex B, page 6 lists the rules of engagement and specifically states "Airborne test firing will be conducted only after obtaining permission from the appropriate clearance authority".

CONFIDENTIAL 12 August 1970

AVBACA-BC 12 August 1970 SUBJECT: Operational Report - Losson Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

The artillery some in which an aircraft is operating can supply information as to free fire zones. Although gunnery practice is encouraged to maintain proficiency, indiscriminate test firing of weapons can result in the loss of life and property and cannot be condened.

- (3) RECOMENDATION: That renewed emphasis be placed on the rules of ongagement with particular stress placed upon airborne test firing of weapons.
- (4) COMMIAND ACTION: Units assigned to the 145th Avn Co (Cbt) have held meetings and discussed this topic in detail. Increased emphasis has been placed on this particular item during the initial "In-Country" orientation for all aviators, crew chiefs and door gunners.

### Avoiding Engine Damage Following Solvent Flush

- (1) OBSERVATION: During the past two months this battalion has had several engine changes due to careless procedures during and following solvent flushes. In all cases an excess of solvent remained in the combustion chamber following flushing, and when the aircraft was subsequently started, the solvent ignited causing hot starts. In one case, the crow thought the engine was on fire and sprayed cold CO2 up the hot end, necessitating an engine overhaul.
- (2) EVALUATION: These situations were caused by a lack of knowledge of correct procedures to be followed when solvent flusing engines.
- (3) RECOMMINDATION: That command emphasis be placed on strict compliance with proper solvent flush procedures. Two important points are: (1) To insure that the combustor is drained of excess solvent by tapping the small square drain on the bottom of the combustion chamber with a screw-driver or wrench, and (2) To insure that proper hot start procedures are followed in case of a hot start, to include continuing to motor the starter and to refrain from using fire extinguishers or water to extinguish flames emitting from the hot end.
- (4) COMMAND ACTION: This specific problem has been discussed in company safety meetings; and the above recommendations have been stressed.

### Communications Security

- (1) OBSERVATION: A considerable amount of operational type information involving flight destination, time sequences, grid co-ordinates, and number of aircraft are being passed in the clear or by unauthorized code systems.
- (2) EVALUATION: The passing of operational type traffic in the clear or by unauthorized code affords the enemy with an abundance of useful information and insight into our operations.

AVBACA-BC

SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

It appears the use of secure voice has decreased with the expectation of the arrival of VNAF aviators.

### (3) RECOMMENDALION:

- (a) That the use of secure voice be emphasized until the VNAF actually assumes all responsibilities.
- (b) That there be a wider dissemenation of KAC-55B (plastic wheels) and keys which allow the aviator to encode or decode operational information in an efficient and accurate manner.
- (4) COMMAND ACTION: Command emphasis is being placed on the continued use of secure voice. Secure voice is utilized at all times between the 145th Avn 8n (Cbt) and company operation sections for passing "need to know" and operational type traffic.

Warm up of the AN/ARC-54 FM radio

- (1) OBSERVATION: Failure of the AN/ARC-54 radio frequently occurs on run up or immediately after the radio is turned on.
- (2) EVALUATION: Keying the transmitter of the AN/ARC-54 FM radio without adequate warm up time will result in damage to the radio.
- (3) RECOMMENDATION: That all aviators allow a minimum warm up period of 3 to 5 minutes before keying the transmitter.
- (4) COMMAND ACTION: Commanders have been informed of the problem and requested to inform their aviators of this information.

### Radio Discipline

- (1) OBSERVATION: During combat assault operations, radio traffic must be kept to a minimum during the period of time the aircraft are on approach to, in and departing the landing zone.
- (2) EVALUATION: On Combat Assaults from 500 feet prior to touchdown until 500 feet on takeoff no transmissions should be made unless fire is received or a flight incident is imminent. The availability of the open frequency will enhance suppressive fire instructions and flight safety. Additionally, strict radio discipline during the initial landing/takeoff phase allows the Aircraft Commanders to better concentrate on their flying and inter-aircraft instructions. If the unit is divided into 2 flights, the flight not involved with the actual insertion/extraction must monitor the radios to know which phase of the combat assault the other flight is involved so as not to tie up the frequency with formation changes, POL activities, Etc.

AVBACA-BC

SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

- (3) RECOMMENDATION: That all units be aware of the situation and evaluate their Standing Operating Procedures.
  - (4) COMMAND ACTION: Flight crews have been briefed on this matter.

Use of Survival Equipment

- (1) OBSERVATION: It had been noted in past accidents that indiviuals involved were left on the ground with only that equipment that was physically on their person at the time of the accident.
  - (2) EVALUATION: None
  - (3) RECOMMENDATION: None
- (4) COMMAND ACTION: Survival vests, FSN 8465-177-4819, were ordered through supply channels and issued to aviators. These vests provide the individual a means to equip himself with the necessary items for survival in an Escape and Evasion situation.

### Drug Abuse

- (1) OBSERVATION: The use of drugs by aviation personnel is becoming a major problem facing all aviation units.
- (2) EVALUATION: The 145th Avn Bn (Cbt) dispensary reports that an estimated 2-3 percent of assigned personnel are currently using herion on a regular basis. As of this time the 145th Avn Bn (Cbt) dispensary has been unable to arrive at a practical plan for the treatment of these individuals in RVN.
- (3) RECOMMENDATION: That USARV take a greater interest in the users of the "Hard Drugs". Also that a treatment center be established in RVN to aid the concerned personnel in breaking the drug habit both mentally and physically.
- (4) COMMAND ACTION: The 145th Avn Bn (Cbt) dispensary has established a series of lectures for all officers and enlisted men of this battalion. These lectures place emphasis on the physiological and pathological harm caused by the drugs most commonly abused in Vietnam. The dangers of "Hard Drugs" such as herion was stressed in these lectures.

### SPH-4 Helmets

- (1) OBSERVATION: Adequate repair parts for the new SPH-4 helmets are not available.
- (2) EVALUATION: Although the new SPH-4 flying helmet has arrived in RVN in large numbers, adequate repair parts/kits for this helmet are not available. As a result of this shorage of repair parts, cannabalization has become the only solution in many cases.

1

AVBACA-BC

SUBJECT: Operational Report - Lesson Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

- (3) RECOMMENDATION: Improve the 145th Avn Bn (Cbt) capability to repair both the SPH-4 and the APH-5 helmets. This could be done by bringing the problem to the proper source and obtaining the needed parts.
- (4) COMMAND ACTION: The supply officer for the 68th Avn Co (Aslt Hel) is presently researching sources in Long Binh Depot in an effort to determine how the needed repair kits can be obtained.

### PSP Pads

- (1) OBSERVATION: Each rainy season, numerous aircraft accidents and incidents occur as a result of wet PSP pads.
- (2) EVALUATION: Each rainy season the safety officer of every unit from the 1st Aviation Brigade down to company level preach the dangers of landing on wet PSP pads. Because this type of material is so readily available it is widely used in MR III.
- (3) RECOMMENDATION: Make the problem known to the owners of these pads through information letters. These letters should point out how hazardous PSP can be when it is wet. It should also point out that antiskid paint is readily available through supply channels.
- (4) COMMAND ACTION: Pilots of this unit have been instructed to speak to various units that utilized PSP pads and bring the dangers of TSP to their attention.

### Operation "Liberty"

The following recommendations for improvement in the transportation of VIP'S is fowarded based upon the cumulative data obtained as a result of Operation "Liberty" conducted 7 June 1970.

- a. The movement of photographers and lesser dignitaries should be facilitated prior to the movement of the main body of VIP's. In this manner, photographs may be taken and there will be no delay in the flow of the tour. This will also prevent congestion at a small heliport, e.g. Red Carpet.
- b. Darkness and inclement weather should be considered. Flashlights had to be brought in to aid in ushering the VIP's to and from the air-craft during the hours of darkness.
- c. Frequencies should be more thoroughly researched to prevent communications interference. Utilization of VHF radios as the primary means of communication rather than UHF, due to the fewer number stations using VHF, is recommended.

12 August 1970

SUBJECT: Operational Report - Lessons Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970 RCS CSFOR-65 (R-2)

d. Recommend that one aircraft in the flight be responsible for artillery. Close monitoring of the artillery frequencies is necessary and a C and C aircraft 10 to 30 minutes ahead of the flight cannot stay abreast of the artillery situation.

4 Incl as

WILLIAM H DILLARD LTC, Infantry Commanding

DISTRIBUTION:

2 - CINCUSARPAC, ATTN: GPOP-DI, APO 96558

3 - CG, USARV, ATTN: AVHGC-DST, APO 96375 2 - CG, 1st AVN BDE, ATTN: AVBAGC, APO 96384 3 - CO, 12th AVN GP (CBT), ATTN: AVBAGA-SC, APO 96266

AVPACA-SC (13 Aug 70) 1st Ind SUBJECT: Operational Report-Lessons Learned, 145th Aviation Battalion (Combat) for the Period Ending 31 July 1970 RCS CSFOR-65 (R2) (U)

DA, HEADQUARTERS, 12TH AVIATION GROUP (COMBAT), APO 96266 2 September 1970

THRU: Commanding General, II Field Force Vietnam, APO 96266

Commanding General, 1st Aviation Brigade, ATTN: AVBA-C, APO 96384

Commanding General, US Army Vietnam, ATTN: AVHGC(DST), APO 96375

Commander-in-Chief, US Army Pacific, ATTN: GPOP-DT, APO 96558

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. (U) This headquarters has reviewed and concurs with the Operational Report-Lessons Learned for the period ending 31 July 1970 from Headquarters, 145th Aviation Battalion (Combat).
- 2. (C) The following comments are provided:
- a. Reference: page 6, para 2c, Mission Coordination. Units are frequently directed by 12th Aviation Group (Combat) Army Aviation Element (AAE) that confirmation of call signs, frequencies, and reporting information is required. The recommended information is now being furnished the aviation units by AAE.
- b. Reference: page 7, para 2c, "Improved AH-IG Oil Cooler Cleaning Procedures". This cleaning procedure is being used by all 12th Avn Gp (Cbt) units as a part of the PMI. During required PMI's and PMP's this headquarters feels the recommendation is valid and should be expanded to include the PMP.
- c. Reference: page 8, para 2c, "VNAF I&M Program". Approval of lateral transfers from I&M units under OPLAN 70-51 are now being approved by G-4, lst Aviation Brigade. In addition, a coordination meeting was held on 20 August 1970 by the S-4, 12th Avn Gp (Cbt) to plan future requirements for units inactivating under the plan.

d. Reference: page 12, Operation Liberty. The recommendations were noted and considered in planning Betsy Ross, a similar operation, which will be presented in the 12th Avn Gp (Cbt) ORLL for the present quarter.

JOHN C. HUGHES COlonel, Infantry

Commanding

AVFBC\_RE (12 Aug 70) 2nd Ind SUBJECT: Operational Report - Lessons Learned of 145th Aviation Battalion (Combat) for Period Ending 31 July 1970 ROS CSFOR\_65 (R2)(U)

DA, HQ, II Field Force Vietnam, APO San Francisco 96266 14 SEP 1970

THRU: Commanding General, 1st Aviation Brigade, ATTN: AVBA\_C APO 96384

Commanding General, US Army Vietnam, ATTN: AVHGC\_DST, APO 96375

Commander\_In\_Chief, US Army Pacific, ATTN: GPOP\_DT, APO 96538

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C. 20310

- 1. (U) This headquarters has reviewed the Operational Report Lessons Learned for the quarterly period ending 31 July 1970 from 145th Aviation Battalion (Combat) and concurs with the comments of the indorsing headquarters.
- 2. (C) Comment follows: Reference item concerning "Communications Security", page 9. COMUSMACV msg 66776, 040552Z Dec 69, authorized RVNAF use of NESTOR equipment, restricted to the use of Headset/Handset only in the presence of cleared US personnel. Joint use of NESTOR equipment is encouraged at all command levels, and is available to US advisory teams down to regimental and province level. Continued use of NESTOR equipment, especially on joint airmobile operations, should be emphasized as long as the aircraft are under US control.

FOR THE COMMANDER:

15

CPI, AGC Asst AG

AVBAGC-0 (12 Aug 70) 3d Ind SUBJECT: Operational Report - Lessons Learned of 145th Aviation Battalion (Combat) for Period Ending 31 July 1970 RCS CSFOR-65 (R2) (U)

DA, HEADQUARTERS, 1ST AVIATION BRIGADE, APO 96384 25 SEP 19/0

TO: Commanding General, United States Army Vietnam, ATTN: AVHGC-DST, APO 96375

- 1. This headquarters has reviewed subject report and concurs with the contents as indorsed.
- 2. The following additional comments are considered pertinent:
- a. Paragraph 2, page 7, addresses problem with oil cooler cleaning procedures on AH-1G aircraft. Concur. TM 55-1520-221-20 does not have a cleaning procedure. This headquarters has requested unit to submit DA Form 2028 (Recommended Change to Military Publications Form) explaining in detail the procedures being currently used.
- b. Paragraph 2, page 7, addresses problem with instrumentation in AH-IG aircraft. Concur. An MMO program is being initiated for AH-IG helicopters which includes MMO 55-152-221-30/19 for an improved attitude indicator.
- c. Paragraph 1, page 9, discusses the necessity for several turbine engine changes due to improper solvent flushing procedures. Concur. This headquarters has recently published procedures for proper cleaning of turbine engines.

CPT, AGC

Asst Adjutant General

FOR THE COMMANDER:

16

AVHDO-DO (12 Aug 70) 4th Ind SUBJECT: Operational Report - Lesson Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970, RCS CSFOR-65 (R-2)

Headquarters, United States Army Vietnam, APO San Francisco 96375 2 DEC 1970

- TO: Commander in Chief, United States Army Pacific, ATTN: GPOP-DT, APO 96558
- 1. This Headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 July 1970 from Headquarters, 145th Aviation Battalion (Combat) and comments of indorsing headquarters.

### 2. Comments follow:

- a. Reference item concerning "Inadequate Instrumentation in the AH-1G Aircraft," page 7, paragraph 2c. The improved attitude indicator MWO is being accomplished at the present time. Maintenance at Vung Tau will modify 224 AH-1G aircraft at the rate of 25 per month. Unit has been so advised.
- b. Reference item concerning "VNAF I&M Program," page 8, paragraph 2c. This Headquarters has coordinated with appropriate agencies to insure necessary action by units deactivating. Unit has been so advised.
- c. Reference item concerning "Avoiding Engine Damage Following Solvent Flush," page 9, paragraph 2c. The correct engine cleaning procedure is in maintenance manuals of the UH-1 and AH-1 aircraft. Compliance with proper procedures will preclude engine hot starts. Unit has been so advised.
- d. Reference item concerning "Drug Abuse," page 11, paragraph 2c: concur. AR 600-32, Drug Abuse Prevention and Control, dated 23 September 1970 states "Limited rehabilitation of restorable drug abusers, when appropriate and consistent with the sensitivity of the mission, will be provided at the lowest unit level possible." A USARV Supplement to AR 600-32, which will include implementing instructions for a rehabilitation program, is being developed by this Headquarters. Currently the 935th and 98th Medical Detachments (Psychiatric Service) at Long Binh and Da Nang respectively provide treatment for hard drug users. In addition, USARV Letter Subject: Medical Technical Guidance, Drug Abuse, outlines medical treatment for drug abusers in Vietnam. Development of a facility for a long term, sustained rehabilitation effort within this command is not in consonance with USARV's mission, nor with the current personnel rotation policy. Recommend Department of the Army develop a rehabilitation center where the narcotic and dangerous drug addict may be sent for long term rehabilitation. Unit has been so advised.

AVHDO-DO (12 Aug 70) 4th Ind SUBJECT: Operational Report - Lesson Learned, 145th Aviation Battalion (Combat), Period Ending 31 July 1970, RCS CSFOR-65 (R-2)

e. Reference item concerning "PSP Pads," page 12, paragraph 2c. This situation was discussed in an October issue of the Aviation Weekly Summary. The FSN for non-skid paint was included. Unit has been so advised.

FOR THE COMMANDER:

Clark W. Stevens Jr.

Captain AGC

Assistant Adjutent Ceneral

Cy furn: 1st Avn Bde 145th Avn Bn GPOP-DT (12 Aug 70) 5th Ind (U)
SUBJECT: Operational Report of HQ, 145th Aviation Battalion (Cbt) for
Period Ending 31 July 1970; RCS CSFOR-65 (R2)


HQ, US Army, Pacific, APO San Francisco 96558 4 JAN 1971

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310

This headquarters concurs in subject report as indorsed.

FOR THE COMMANDER IN CHIEF:

L.M. OZAKI CPT, AGC Asst AG



145th Ariation Battalion (Combat) 31 July 1970 Unit Strength

UNIT	OFFICER AUTH 0/	CER O/H	HLOV	¥0 0/H	AUTH EM	њo	TOTAL	H/0	NV AU TH	п/о
68th Aslt	19	16	द	\$	218	242	288	307	19	20
118th Aslt	19	16	22	84	218	243	288	307	~	2
190th As1t	19	10	22	92	218	3	832	82	8	3
334th Atk	17	19	8	42	198	506	254	249	16	7
HHC	19	ผ	<b>m</b>	80	88	128	108	157	17	16
Sety Mt	0	0	0	0	88	7	28	3	٥	0
430th Med	-	H	0	0	~	2	Φ	Φ	0	0
520th Med	-	9	0	o	~	9	Φ	9	0	0
391st QN	•	0	0	0	80	10	80	10	0	0
324th ASD	<b>e</b> 1	<b>4</b>	0	0	16	13	17	14	0	0
In Btal	%	Ŕ	195	157	1004	920	920 1295	1171	57	15

21

HEADQUARTERS, 145TH AVIATION BATTALION (COMBAT)
31 July 1970
AIRCRÆT STATUS

	4.5	-	181 4	-	יות לה	c	114_1H	11	AH	AH-1G	i.O	03-58A
SUBORDINATE UNIT	AUTH 0	14/0	AUTH C	, H	HIL	14/0	HINY P/C	H/O	DI I	E/0	HILLY	10/H
HiC, 145th AB(C)	0	0	0	0	0	0		-	0	0	<b>m</b>	3
68th Avn Co (Aslt Hel)	0	0	80	~	0	4	23	17	0	0	0	0
118th Avn Co (Aslt Hel)	0	0	80	9	0	7	23	16	0	0	0	0
190th Arm Co (Aslt Hel)	0	-	æ	0	0	7	23	12	0	0	0	0
334th Avn Co (Atk Hel)	0	0	0	0	0	-	3	-	27	17	0	0
SATTAION TOTALS	0	-	₩ <b>7</b> 2	13	0	16	23	47	27	17	0	3
						I		1				

22

CONFIDENTIAL

145TH AVIATION BATTALION (COMBAT) 1 MAY - 31 JULY 1970 OPERATIONAL STATISTICS

•												
	SUBORDINATE UNIT	HOURS	SORTEES FLOWN	PAX	CARGO TOTIS	WAY (KBA)	SIRUCIURES DAW DST	SC SU DS T	SAMPANS DAM DS	ANS	AIRCHAFT DAM DS	AFT DST
	58th Avn Co (Aslt Hel)	7.532	19,7% 141,242	141 242	149	0	22	17	0	0	ĵ	-
	118th Avn Co (Aslt Hel)	3,025	23,774 53,964	196.65	65	04	32	52	0	0	4	9-1
23	190th Avn Co (Aslt Hel)	7.351	19.250	41 .407	123	9	56	30	0	0	4	4
	334th Avn Co (Atk Hel)	3,652	6,015	369	23	342	81	279	2	7	3	0
	-HC. 145th Am Bn (Cbt)	727	2,451	386	14	0	0	0	O	o	0	0
	SALTOT HOLD TOTALS	27.587	71.256	71.256 138.458	374	388	161 378	378	2	7	14	9

### UNCLASSIFIED

Security Classification	
DOCUMENT CO	NTROL DATA - R & D
	ing annutation must be entered when the overall report in classical
DORIGINATING ACTIVITY (Corporate author)	28. REPORT SECURITY CLASSIFICAT OF
HQ DA, OACSFOR, Washington, D.C. 2031	O CONFIDENTIAL
	28. GROUP
	4
S. REPORT TITLE	
Operational Report - Lessons Learned, H	0 145th Aviation Battalion
Operational Report - Lessons Learned, in	Q, 145th harmeron paccarron
4. DESCRIPTIVE NOTES (Type of report and inclusive dates)	
Experiences of unit engaged in counteri	nsurgency operations 1 May to 31 July 1970
S AUTHORISI (First name, middle initial, last name)	
CO, 145th Aviation Battalion	
(O, 145th Aviation Battalion	
6. REPORT DATE	78. TOTAL NO OF PASES TO. NO. OF REFS
.2 August 1970	26
2 August 1970	SO. ORIGINATOR'S REPORT NUMBER(S)
b. PROJECT NO.	
M/A	703266
c. N/A	90. OTHER REPORT NOIS) (Any other numbers that may be seeigned
	this report)
d	
10 DISTRIBUTION STATEMENT	
II. SUPPLEMENTARY NOTES	12. SPONSORING MILITARY ACTIVITY
N/A	DA, OACSFOR, Washington, D.C. 20310
	20320
ID. ABSTRACT	<del></del>
	24

DD . 1473

UNCLASSIFIED
Security Classification